

STATE OF MINNESOTA

Department of Public Safety - Bureau of Criminal Apprehension
1430 Maryland Ave. East St. Paul, MN 55106**MINNESOTA DUTY OFFICER**

Bureau of Criminal Apprehension Operations Center

Report #: 148048

Report Date: 2/16/2015

Report Time: 11:58

DO#: 33

CALLER INFORMATION

Contact: Bruce Trebnick

Company: Northeast Technical Services (NTS)

Address: P.O. Box 1142

City: Virginia

State: MN Zip: 55792-

Phone: (218) 780-2006 Ext:

Alt phone: Ext:

Have local police and/or fire been notified?

NARRATIVE

time system pumps run for a period of time, Caller reporting the time system pumps didn't auto start sometime last night, which caused seepage to run out of containment to the overflow pipe. This happened sometime yesterday but was not discovered until 8:00 this morning and then the pump had to be manually started. The cause is under investigation and RP will continue to monitor. It released into Second Creek which is part of the Embarrass River Water Shed. There are no downstream users. There is a discharge monitoring point 1/4 mile downstream and samples were taken at that point. This is water that would normally be released through the watershed, but not in this volume. RP did check downstream for increase flow and saw very little impact. In the headwaters there are a number of Beaver dams which help slow down the flow.

INCIDENT REPORT: SPILLS**RESPONSIBLE PARTY/PROPERTY OWNER**

Contact: Andrea Hayden

Company: Cliff's Natural Resources

Address: County Rd 666, PO Box 900

City: Hoyt Lakes

State: MN

Zip: 55750-090

Phone: (218) 226-6032 Ext:

Alt phone: Ext:

SPILL INFORMATION

Material: seep water

Quantity: est > 144,000 gallons

Incident date: 2/16/2015

Time:

Is the spill ongoing? No

SPILL LOCATION

Name: Cliff's Erie LLC - Hoyt Lakes Plant

Address: County Rd 666

City: HOYT LAKES

County ST. LOUIS

Section:

Range:

Township:

Legal:

Released to: Surface Water

Spill area: Industrial

Have any sewers been impacted? no

Surface waters impacted? Second Creek

If A.S.T. is involved, is there secondary containment around the tank?

Type:

Kind of spill: Spill/Release

Has the material escaped the location property? Yes

ANY QUESTIONS - PLEASE CONTACT THE MN DUTY OFFICER AT 651-649-5451 or 800-422-0798

Has the released material been contained? Yes Is this a SARA Title, Section 304 release?
 Is a CAT/ERT being requested? No

In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2/16/2015	12:35	MPCA On-call		Phone
Narrative: Jim Stockinger cell - left msg with details, if any questions call DO. DO will send a copy							
In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2/16/2015	12:35	MPCA Metro		Email
Narrative: cc'd Jim Stockinger							
In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2/16/2015	12:36	DNR		Fax
Narrative:							
In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2/16/2015	12:36		ST. LOUIS	Fax
Narrative:							
In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2/16/2015	12:37	MPCA Metro		Email
Narrative: Email button clicked							